

Oil Field Environmental Incident Summary

Incident: 20131215153939

Date/Time of Notice: 12/15/2013 15:25

Responsible Party: Continental Resources

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: MALCOLM 4-20H1

Field Name: SAUK

Well File #: 25480

Date Incident: 12/14/2013

Time Incident: 14:45

Facility ID Number:

County: WILLIAMS

Twp: 159

Rng: 95

Sec: 20

Qtr:

Location Description: Cultivated field.

Submitted By: Patrick Skillestad

Received By:

Contact Person: Patrick Skillestad
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	0	barrels	0	barrels		
Other	50	barrels	0	barrels		

Description of Other Released Contaminant:

Fresh water mixed with biocide.

Inspected:

Written Report Received: 10/14/2016

Clean Up Concluded: 12/15/2013

Risk Evaluation:

None

Areal Extent:

Topsoil in cultivated field.

Potential Environmental Impacts:

No anticipated impact to location soil or topsoil in cultivated field.

Action Taken or Planned:

Valve was shut and all other valves on frac tanks were checked to make sure they were closed. Nothing has been done for cleanup as the water froze almost instantly. Landowner looked at spill in his field and was not concerned. He agreed that we would re-evaluate the spill in his field in the spring.

Wastes Disposal Location: None recovered

Agencies Involved:**Updates**

Date: 12/16/2013 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spray off location. Followup is necessary.

Date: 1/10/2014 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 13:09 1/10/14.

No visible sign of spill at the well location.

Since the spill involved biocide, a followup is necessary in the spring (May most likely) of 2014 to discern any negative impacts to the surrounding land.

Date: 2/7/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

2/7/14 - 16:55 on location. Appears that the water went off the SE corner of the pad and into the field. No surface waterbodies are in the immediate area. No adverse impacts are expected. No further inspection required.

Date: 3/9/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 9, 2016.